Attorney Docket No.: 291958107US2

by certify that this correspondence is being deposited with the U.S. Postal Service with sufficient postage as st Class Mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-

1450. on:

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: KYLE M. HANSON

PATENT No.:

6.761.806 BZ

ISSUED:

JULY 13, 2004

FOR: PROCESSING APPARATUS WITH

SENSORY SUBSYSTEM FOR DETECTING THE PRESENCE/ABSENCE OF WAFERS

OR OTHER WORKPIECES

EXAMINER:

DONALD R. VALENTINE

ART UNIT:

1742

CONF. No.: 4760

Request for Certificate of Correction under 37 C.F.R. §1.322 or §1.323

Certificate OCT 0 5 2004

of Correction

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

- The applicant(s) requests a Certificate of Correction to correct errors in the 1. above-identified patent, which are listed on the enclosed Form PTO/SB/44.
- Any errors on the part of the applicant are of a clerical or typographical nature or 2. are otherwise minor in character. None of the requested corrections would constitute new matter or require reexamination of the patent.
- Source of Error(s) and Payment of Fee: 3.
 - All of the errors listed on Form PTO/SB/44 are believed to be due to \boxtimes mistake on the part of the USPTO (37 C.F.R. §1.322). Accordingly, no fees are believed to be due.
 - At least one of the errors occurred due to applicant's mistake made in П good faith (37 C.F.R. §1.323).
 - A check covering the fee under 37 C.F.R. §1.20(a) (\$100.00) is enclosed herewith

- Please charge the fee under 37 C.F.R. §1.20(a) to Deposit Account No. 50-0665. This paper is provided in triplicate.
- Please charge any underpayment necessary for consideration of this paper to Deposit Account No. 50-0665.
- 4. Please send the Certificate of Correction to the undersigned at the address shown below.

Respectfully submitted, Perkins Coie LLP

Date: September 27, 2004

Paul T. Parker

Registration No. 38,264

Correspondence Address:

Customer No. 25096 Perkins Coie LLP P.O. Box 1247 Seattle, Washington 98111-1247 (206) 359-8000

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,761,806 B2

DATED: July 13, 2004

INVENTOR(S): Kyle M. Hanson

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 24

Line 7, "in" should be --on--; Line 11, "tin" should be --in--;

Column 36

Line 7, "Placing" should be --Plating--;

MAILING ADDRESS OF SENDER:

Perkins Coie LLP PATENT-SEA PO Box 1247 Seattle, WA 98111-1247 PATENT NO.

No, of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, Washington, DC 20231.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,761,806 B2

DATED: July 13, 2004

INVENTOR(S): Kyle M. Hanson

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 24
Line 7, "in" should be --on--;
Line 11, "tin" should be --in--;

Column 36
Line 7, "Placing" should be --Plating--;

MAILING ADDRESS OF SENDER:

Perkins Coie LLP
PATENT-SEA
PO Box 1247
Seattle, WA 98111-1247

PATENT NO.

No. of additional copies

____> ¹

Burden Hour Statement: This form Is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, Washington, DC 20231.